

This firmware update is for all D756USTi and DH759USTi Ultra Short Throw Projectors

Fixes & Improvements:

- Fixed calibration not working correctly on Windows 10
- Fixed double click not working on Windows 10 (build 1607) Anniversary update and above
- Improved ambient light handling
- Improved tracking

Note:

[NovoPointer version 2.1.42.203](#) **needs** to be installed on the computer before continuing to update process.

1. Download & prepare


Preparation:

1.1 Download the firmware file from the link below:

① Firmware: [Download](#)

2. Update Process

2.1 Update the firmware




- 1) Start the NovoPointer application
- 2) Click on the “**Settings**” button

Note:

For the next update step, your status must be shown as “connected”. Re-connect the USB cable to the projector if the menu shows ‘Disconnected’.




3) Click on the “IM Upgrade” button.



4) Select the bin file:
① (interactive_module20171020_FP05.bin)

DO NOT UNPLUG OR SHUT DOWN THE COMPUTER DURING THE UPGRADE PROCESS



5) The update progress message will be displayed. Wait for the update to complete to 100 percent



6) Once the update completed, click on the “Reset” button.

Note:

If USB does not connect after pressing reset, unplug the USB cable and reconnect it.


3. Confirm the version of the software

3.1 Confirm if your firmware update has been done successfully by reading the firmware version.



- 1) Go to Settings on the main menu of NovoPointer.
- 2) Confirm the version by clicking on the “Get IM Ver” button.

The latest version is **20171020_FP05**



The update is now completed!